TIME 9:25 AM
DATE 02/29/94
SUBTOTAL 3427 LB
TOTAL 9427 LB
WORLD RESDURCES CO.

171 700

9:25 AM 02/29/94

# WORLD RESOURCES COMPANY

8113 WEST SHERMAN STREET / PHOENIX, ARIZONA 85043 / (602) 233-9166

Mr. Gerald A. Thompson Alaskan Copper Works 628 South Hanford Street Seattle, Washington 98134

Dear Mr. Thompson:

Enclosed is the appropriate copy of the Uniform Hazardous Waste Manifest and the weigh ticket resulting from the transfer of the recyclable materials by your company to World Resources Company (WRC) and the transportation of these recyclable materials to the WRC Recycling Facility in Arizona for the purpose of recovering the metal values therein.

Sincerely,

WORLD RESOURCES COMPANY

2 Piergallini

Manifest Coordinator

**Enclosures** 

	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. W   A   D   9   8   0   7   3   8   5   4	Manifest Docume	nt No.		Page 1			n the shaded area d by Federal law.
3.	Generator's Name and Mailing Address	[W] A  D  9  6  0  /  3  6  3  4	01 9410	101.	33,700,000,000		nifest D	ocumer	nt Number
	ALASKAN COPPE								
	3200 Sixth Aven	그가 그런 일을 하는 것으로 살아왔다면 그는 그들 일을 잃어왔다면 그리고 있다면 그렇게 되었다.	8134		B. S	State Ge	nerator's	s ID	
	Generator's Phone (206) 62 Transporter 1 Company Name	3 <b>–</b> 5801 6. US EPA ID	Number		lo s	State Tra	ansporte	r'e ID	
٥.	C.K.C. Incorpora			111					08) 627-259
7.	Transporter 2 Company Name	8. US EPA ID		NA.	E. S	tate Tra	nsporte	r's ID	007 UE [=2,39
				$\coprod$	TANGE TO THE RE	THE SECOND OF LINES OF	ter's Pho	NAME OF BEHINDING	
9.	Designated Facility Name and Site Address		Number		G. S	State Fa	cility's ID	)	
	World Resources 8113 West Sherm				lu e	acility's	Phone		
	Phoenix, Arizon		13  5  5	lo lo	)		602) 23	22_01	66
			12		ainers		13. otal	14.	1.
11	US DOT Description (Including Proper SI	ipping Name, Hazard Class and ID Num	iber)	No.	Туре	Qu	otai antity	Unit Wt/Vol	Waste No.
a.	A STATE OF S								
	RQ, Hazardous wa		l l	o b		4 3	d da		
э.	(F006), 9, NA3077		<u> </u>	υр	CIF	43	8 27	I P	F006
Ο.	RQxxHezendousxwa	atenned iskanoman							
	AACKARIK KAXXXBBBCKX		kxt	XXXX	<b>AXXXX</b>	xxxx	xxxxxx	XXXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Э.									5001
				116/A <sub>16</sub> )				1	
d.									
						1 1 1	1 1	Accountable of	
J.	Additional Descriptions for Materials Liste	d Above			К. На	ndlina (	Codes to	r Waste	es Listed Above
P	.O # M33276					0		6 (e)	
_	Special Handling Instructions and Addition	onal Information							544400000000000000000000000000000000000
	*** 21	HOUR EMERGENCY RESPON	ISE: 1-	(800	) 424	-9300	CHE	MTRE	C ***
		WEAR GOGGI							
16	GENERATOR'S CERTIFICATION.	The the contests of this cont	and accurate	, doc	ibad sh	vo bu		The second	
10	<b>GENERATOR'S CERTIFICATION:</b> I hereby declare proper shipping name and are classified, packed, in	marked, and labeled, and are in all respects in pr					у		
	according to applicable international and national of I am a large quantity generator, I certify that		ime and toxic	ity of	waste oe	enerated	to the dec	aree I ha	ave determined to be
	economically practicable and that I have select future threat to human health and the environm	ed the practicable method of treatment, storage	ge, or dispos	al cur	ently av	ailable to	me which	h minim	izes the present and
	the best waste management method that is availa		nave made a	good	iaim ein	ort to mil	nimize my	waste ç	generation and select
	Printed/Typed Name	Signature	10	1			A. San Trans.		Month Day Yea
_	ERALD A. THOMPSON	- Lang	17				2		0 2 2 3 9 4
17.	Transporter 1 Acknowledgement of Reco			3					
3	Printed/Typed Name	Signature 12/14 12	Pot	Ma					Month Day Year
18	Transporter 2 Acknowledgement of Rece	eint of Materials	100		1,,,	14.1	The State of	1,	02239
	Printed/Typed Name	Signature			NA.				Month Day Year
9.	Discrepancy Indication Space								
0.	Facility Owner or Operator: Certification		ed by this n	nanife	st exce	pt as no	oted in It		Self-result for the
	Printed/Typed Name	Signature	)(	70	) /	0			Month Day Year
	UATIVIDAD DIAZ		10	ac	/ a	uo	3		030199

Style CF17-6 Printed by LABELMASTER, Div. of AMERICAN LABELMARK CO., CHICAGO, IL 60646 (800)621-5808

EPA Form 8700-22 (Rev. 9-88) Previous editions are obsolete.

1000000	INIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.  W   A   D   Q   8   D   7   3   8   5		Manifest Document No.	2. F	1		the shaded area d by Federal law.
4. Gen	nerator's Name and Mailing Address ALASKAR COPPE 3200 SINTH AVE 11 nerator's Phone (206 ) 62	R WORKS ie South Scattle WA 3-5801	981	34	A. S	te te Manifest I	r's ID	t Númber
	nsporter 1 Company Name <u>C.K.C., Incorpora</u> nsporter 2 Company Name	ted CADSS	A ID NO O 5 II PA ID NO	8 4 5 11 6	D T	late Transport	hone <b>( )</b> ers ID	08) 627-2595
9. Des	signated Facility Name and Site Addre World Resources 8113 West Sherm Phoenix, Arizon	Company an Street	A ID No.		G. S	ransporter's Pl taté Facility's actliny's Phone (602) 2	Ď	66
11. UŞ	DOT Description (Including Proper Sh			12, Cont	ainers	13. Total	14. Unit	Waste No.
a.	9G, Hezardous wa (8806), 9, NA3077			No.	Type C F	Quantity	Wt/Vol	F006
o	200 H330550 H3377 2200 GGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGG	ව්රෑගම්බ්ජිවේරවාවිය රෙවරු		popodo	dexiax.	<u>lodododod</u>	CXKEXX	EDE SERVICES
5.   						1111		
	en e		un de grioù fer ar a h	nerskepadžija addienia alieni, edigaji, pr	l T		ara zadnia se na propi d	
	egardisu kin bunten esemate. 1-220 E.S. Environmental	nt storage and disposer sected by several the form Seins comments of the form Seins comments. Policy Branch, Ph. C.C. 20400, and to the Chick of the trans. O.C. 20400.	Ven Drie O or in	d Complaind ind this bende at SW Wash	10 (5) 10 (6) (7) 10 (6) (8)	płodulky Trodukych TCA yboku	Manager Manager Manager	
P.Ol	6 pc21276 ecial Handling Instructions and Additi	onal Information HOUR EMERGENCY RES	PONS	E: 1-(890	) 424	-9300 CHE		
16. GEN prope account 1 1 confutnition	6 pc21276 ecial Handling Instructions and Additi	that the contents of this consignment are narked, and labeled, and are in all respect povernment regulations.  I have a program in place to reduce the edithe practicable method of treatment, ent; OR, if I am a small quantity generable to me and that I can afford.	FONS OGCLE fully and ts in prop e volume storage, ator, 1 hav	E: 1-(800 S AND GL accurately describer condition for to and toxicity of or disposal cur	OVES	ve by bighway	MTRE	ve determined to be
16. GEN prope accol future the b Print GERA	ecial Handling Instructions and Addition and	e that the contents of this consignment are narked, and labeled, and are in all respect povernment regulations.  I have a program in place to reduce the determinent of treatment, ent; OR, if I am a small quantity generate to me and that I can afford.  Signature	FONS OGCLE fully and ts in prop e volume storage, ator, 1 hav	E: 1-(800 S AND GL accurately describer condition for to and toxicity of or disposal cur	OVES	ve by bighway	egree I ha	ve determined to be
16. GEN proper account the b Print GERA	ecial Handling Instructions and Addition and	prial Information  HOUR EMERGENCY RES  WEAR GO  In that the contents of this consignment are marked, and labeled, and are in all respect povernment regulations.  I have a program in place to reduce the difference of treatment, ent; OR, if I am a small quantity generalle to me and that I can afford.  Signature	fully and ts in prope e volume storage, ttor, I have	E: 1-(800 S AND GL accurately describer condition for to and toxicity of or disposal cur	OVES	ve by bighway	egree I ha	ve determined to be zes the present and eneration and select
16. GEN properacco if I a econ future the b Prin GERA 17. Tran	ecial Handling Instructions and Addition 2 decial Handling Instructions and Addition 2 decial Handling Instructions and Addition 2 decial Handling Instructions and Additional English Packed, ording to applicable international and national am a large quantity generator, I certify that indinically practicable and that I have select the threat to human health and the environmoest waste management method that is availanted/Typed Name  THAPSON INSPORTED 1 Acknowledgement of Reconted/Typed-Name	onal Information  HOUR EMERGENCY RES  WEAR GO  In that the contents of this consignment are marked, and labeled, and are in all respect povernment regulations.  I have a program in place to reduce the difference of treatment, ent; OR, if I am a small quantity generable to me and that I can afford.  Signature of Materials  Signature  Signature	fully and ts in prope e volume storage, ttor, I have	E: 1-(800 S AND GL accurately describer condition for to and toxicity of or disposal cur	OVES	ve by bighway	egree I ha	ove determined to be zes the present and eneration and select
16. GEN prope accol if I is econ future the b Prin GERA 17. Trai	ecial Handling Instructions and Addition 24  ERATOR'S CERTIFICATION: I hereby declar er shipping name and are classified, packed, ording to applicable international and national am a large quantity generator, I certify that indinically practicable and that I have select the threat to human health and the environmoest waste management method that is availanted/Typed Name  ID A. THOMPSON  INSPORTED TACKNOWLEDGEMENT OF RECEIVED.	onal Information  HOUR EMERGENCY RES  WEAR GO  In that the contents of this consignment are marked, and labeled, and are in all respect povernment regulations.  I have a program in place to reduce the difference of treatment, ent; OR, if I am a small quantity generable to me and that I can afford.  Signature of Materials  Signature  Signature	fully and ts in prope e volume storage, ator, I have	E: 1-(800 S AND GL accurately describer condition for to and toxicity of or disposal cur	OVES	ve by bighway	egree I ha	ove determined to be zes the present and eneration and select Month Day Year Month Day Year
16. GEN prope according the b Print GERA 17. Trai Print Prin	ecial Handling Instructions and Addition 2 decial Handling Instruction 3 decial Hand	onal Information HOUR EMERGENCY RES WEAR GO  In that the contents of this consignment are marked, and labeled, and are in all respect jovernment regulations.  I have a program in place to reduce the ed the practicable method of treatment, ent; OR, if I am a small quantity genera ble to me and that I can afford.  Signatur  eight of Materials  Signatur	fully and ts in prope e volume storage, ator, I have	E: 1-(800 S AND GL accurately describer condition for to and toxicity of or disposal cur	OVES	ve by bighway	egree I ha	ve determined to be zes the present and eneration and select  Month Day Year  Month Day Year  O 2 2 3 4
16. GEN prope according the b Print GERA 17. Train Print Pri	ecial Handling Instructions and Addition 2 decial Handling Instruction 3 decial Hand	that the contents of this consignment are marked, and labeled, and are in all respect povernment regulations.  I have a program in place to reduce the ed the practicable method of treatment, ent; OR, if I am a small quantity generable to me and that I can afford.  Signature spirit of Materials  Signature Signature  Signature Signature  Signature	fully and ts in prope e volume storage, ator, I have re	E: 1-(800 S AND GL accurately describer condition for the and toxicity of or disposal curve made a good	OVES  Tibed aboransport I  waste governity averaged faith eff	ve by bighway enerated to the dailable to me whort to minimize n	egree I haich minimi	ve determined to be zes the present and eneration and select  Month Day Year  Month Day Year  O 2 2 3 4

### **NOTICE**

TO: World Resource Company

8112 West Sherman Street Phoenix, Arizona 85043

From: Alaskan Copper Works

628 South Hanford Street Seattle, Washington 98134

SUBJECT: Land Disposal Restriction Notice

Manifest Number:	94001	
Date of Shipment:	2/23/94	

This shipment of material, which is being provided for recycling, is subject to the land disposal restrictions of 40 CFR, Part 268, Subpart D or the prohibitions specified in 268.32 or RCRA 3004(d). The applicable Land Disposal Restriction Information is provided in accordance with 40 CFR 268.7 and is shown below:

EPA Material	Regulated	Subcategory	Treatability	Treatmen	t Standards
Number	Constituent		Group	CFR Reference	Prohibition Level
F006	N/A	N/A	Nonwastewater	40 CFR 268.41 40 CFR 268.43	
				•	

By: Gerald A. Thompson

Alaskan Copper Environmental Assistant

### **MATERIAL IDENTIFICATION**

DOT SHIPPING NAME:

Hazardous Waste Solid N.O.S. (F006)

DOT HAZARD CLASS: UN OR NA NUMBER: Class 9 NA 3077 1990 EMERGENCY RESPONSE GUIDE

## **DOT EMERGENCY RESPONSE GUIDE 31**

### **POTENTIAL HAZARDS**

### FIRE OR EXPLOSION

Some of these material may burn, but none of them ignites readily.

### **HEALTH HAZARDS**

Contact may cause burns to skin and eyes.

Fire may produce irritating or poisonous gases.

Runoff from fire control or dilution water may cause pollution.

### **EMERGENCY ACTION**

Keep unnecessary people away.

Isolate hazard area and deny entry.

Self-contained breathing apparatus (SCBA) and structural firefighters,s protective clothing will provide limited protection.

**CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE**.(Use Chemtrec Company Code "WORR") If water pollution occurs, notify the appropriate authorities.

### FIRE

Small Fires: Dry chemical, CO2, Halon, water spray or standard foam.

Large fires: Water spray, fog or standard foam is recommended.

Move container from fire area if you can do it without risk.

Do not scatter spilled material with high-pressure water streams.

Dike fire control water for later disposal.

### SPILL OR LEAK

Stop leak if you can do it without risk.

Small Dry Spills: With clean shovel place material into clean, dry container and cover, move containers from spill area.

**Small spill:** Take up with sand or other noncombustible absorbent material and place into containers for disposal.

Large Spills: Dike far ahead of liquid spill for later disdosal.

Cover powder spill wiuth plastic sheet or tarp to minimizing spreaing.

#### **FIRST AID**

In case of contact with material, immediatly flush eyes with running water for at least 15 minutes.

Wash skin with soap and water.

Remove and isolate contaminated clothing and shoes at the site.

NOTE: If this response guide is	used as an attachment for shipping documents,	enter shipping
manifest number in block below.		]
	WAD980738546_94001	5
	(Shipping Manifest Number)	J

## **Material Safety Data Sheet**

F006 Recyclable Material (Filter Cake)

Recycler's Facility Name and Site Address:

World Resources Company

8113 West Sherman Street Phoenix, Arizona 85043 Tele: 1-602-233-9166 Fax: 602-936-9164

Issued: 8/7/90 Revised: 9/15/93 - DLS

Call CHEMTREC only in the event of emergencies during shipping that involve a spill, leak, fire, or accident (all calls are recorded)

For Emergencies During Shipping in the US or Canada, Day or Night, Call: CHEMTREC 800-424-9300 (Use Chemtrec Company Code "WORR") For calls from other countries call: 202-483-7616 Collect

#### Section 1

### PRODUCT - MATERIAL IDENTIFICATION

Generic Name: Electroplating/Metal-Finishing Wastewater Treatment Sludge DOT Shipping Name: RQ, Hazardous waste, solid, n.o.s., (F006) Environmental Protection Agency (EPA) Waste Classification: F006

Chemical Family: Metallic (Hydroxide) Precipitates Synonym: Non-ferrous Metal Hydroxide Filter Cake DOT Hazard Class: 9 Packaging Group III

DOT Identification Number: NA 3077 **DOT Emergency Response Guide 31 Applies** 

### Section 2

Section 2			MAZAND	OUS INGREDIEN IS
Ingredient:	CAS Number:	Content %:	ACGIH-TLV	Toxicology: (rat, oral)
Copper Hydroxide	20427-59-2	0-30	1.0 mg/m3 (Dust)	LD-50 1,000 mg/kg
Nickel Hydroxide	12054-48-7	0-15	1.0 mg/mg (Dust)	LD-50 1,500 mg/kg
Calcium Hydroxide	1305-62-0	0-15	5.0 mg/m3 (Dust)	LD-50 7,340 mg/kg
Diatomaceous Earth	68855-54-9	0-10	6.0 mg/mg (Dust)	LD-50 3,160 mg/kg

### Section 3

### PHYSICAL AND REACTIVITY DATA

HAZARDOUS INCRE

Description: Solid, Clay-like Clumps,

Gray/Green to Brown,

Water Content 30-80% Specific Gravity: 1 to 1.4 Solubliity: Insoluble in water

Flashpoint: Nonflammable

Density: 64 to 90 lbs/cu/ft

Incompatible Reactivity: None Known

Vapor Pressure: Insignificant Stability: Avoid contact with acids Polymerization: Will not occur

Boiling Point: Above 2600°C Melting Point: Above 1800°C

FIRE AND EXPLOSION DATA

pH: 7.0 to 10.0 Odor: Nil

#### Section 4

## Oxidation: Non-oxidizing

Special Firefighting Procedures: None Product Decomposition. . . . . (Due to Fire or Explosion): None

Explosive: Non-explosive

NFPA Fire Diamond



#### Section 5

### TOXICITY

Listed Carcinogen component: Nickel

Toxicology: See Sec. 2 (Nickel Hydroxide)

Route of Entry: Inhalation and Ingestion

#### Section 6

### HEALTH EFFECTS AND FIRST AID

Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry. Induce vomiting (do not induce vomiting or give a liquid to an unconcious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term Effects: Chronic overexposure may affect the following target organs or body systems-blood, digestive, respiratory, lungs, liver.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage and metal-sensitive skin or skin lesions.

#### Section 7

### PRECAUTIONS FOR SAFE HANDLING

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment be used by personnel who will come in contact with the material. The squipment should include eye protection, respirator and gloves.

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover from rain.

Spills: Cleaning procedures should not create excessive dust. Vacuum when possible. Package material and send to World Resources Company at above address.

#### Section 8

### CONTROL MEASURES

Respiratory Protection: NIOSH-MSHA approved respirators as required. Other Protective Equipment: Coveralis are recommended, but not required. Eye Protection: Safety Glasses recommended. Rand Protection: Gloves recommended.

#### Section 9

### GENERATORS VERIFICATION

This MSDS is provided solely for informational purposes and no warranty or responsibility is extended even though reasonable precautions have been taken in the preparation of the data contained for this recyclable material. To the best of my knowledge this MSDS describes the recyclable material listed on the attached Manifest Number: Works 628 sixth ave. south

Sunature:

AZF-WRC 9/93



# Recyclable Material

	Container				Waste	
US DOT Description	No.	Туре	Quantity	Unit	No.	
RQ, HAZARDOUS WASTE, SOLID N.O.: (F006), 9, NA3077, III	3.	CF	3827	P	F006	
				ä		
		Total	3827			

Weigh

Verified

By: Susan Wintermite